







2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com

INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE









2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com

CLIPS FOR SNAP-ON TRIM PROFILE



CLIPS

Scale: N.T.S. Dwg File: SOCLIPS.dwg.




2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com

INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE




ELEVATION VIEW

DOOR STOP
IS NOTCHED
AT JAMB

1

DOOR JAMB TO DOOR HEADER

CC1 CLIPS - 2 REQUIRED




ELEVATION VIEW

2

DOOR HEADER AND GLAZING HEADER
TO DOOR JAMB

TC2 CLIPS - 2 REQUIRED


NOTE: ALL TRIM, EXCEPT 1", WILL NEED TO
BE NOTCHED AT THIS CLIP (SEE DETAIL 7)



2A

DOOR HEADER AND GLAZING HEADER
TO DOOR JAMB

FC1 CLIPS AND SC1 CLIPS - 2 REQUIRED EACH



3

GLAZING HEADER TO JAMB MULLION

CC1 CLIPS - 2 REQUIRED




2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com

INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE




4

SILL TO DOOR JAMB

FC1 CLIPS – 2 REQUIRED

NOTE: ALL TRIM, EXCEPT 1", WILL NEED TO
BE NOTCHED AT THIS CLIP (SEE DETAIL 7)


ALLOW 1/8"
CLEARANCE
FOR TRIM.



4A

SILL TO DOOR JAMB

SC1 CLIPS – 2 REQUIRED




5

SILL TO JAMB MULLION

FC1 CLIPS – 2 REQUIRED

NOTE: ALL TRIM, EXCEPT 1", WILL NEED TO
BE NOTCHED AT THIS CLIP (SEE DETAIL 7)

ALLOW 1/8"
CLEARANCE
FOR TRIM.



5A

SILL TO JAMB MULLION

SC1 CLIPS – 2 REQUIRED







2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com

INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE






2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax


110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com


INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE




8A HORIZONTAL MUNTIN TO JAMB MULLION
SC1 CLIPS – 2 REQUIRED



9 HORIZONTAL MUNTIN TO VERTICAL MULLION
FC1 CLIPS – 2 REQUIRED EACH
NOTE: ALL TRIM, EXCEPT 1", WILL NEED TO BE NOTCHED AT THIS CLIP (SEE DETAIL 7)



9A HORIZONTAL MUNTIN TO VERTICAL MULLION
SC1 CLIPS – 2 REQUIRED EACH



10 HORIZONTAL MUNTIN TO DOOR JAMB
FC1 CLIPS – 2 REQUIRED
NOTE: ALL TRIM, EXCEPT 1", WILL NEED TO BE NOTCHED AT THIS CLIP (SEE DETAIL 7)




2301 E. Vernon Ave.
Vernon, CA 90058
866.443.7258
323.908.5430
323.908.5451 Fax

7601 Ambassador Row
Suite 102
Dallas, TX 75247
214.295.2165
214.496.0156 Fax

110 Viaduct Rd
Stamford, CT 06907
203.316.8033
203.316.0019 Fax

www.wilsonpart.com


INSTALLATION CLIPS FOR SNAP-ON TRIM PROFILE



10A

HORIZONTAL MUNTIN TO DOOR JAMB

SC1 CLIPS – 2 REQUIRED




11

TRANSOM HEADER TO
DOOR JAMB AND JAMB MULLION

SC1 CLIPS – 2 REQUIRED

FC1 CLIPS – 2 REQUIRED



12

SILL TO JAMB MULLION

CC1 CLIPS – 2 REQUIRED